

## Motor Replacement Chart

Model Number on Motor	Used on	Equalizer Replacement Part Number	Comments
MF4042	EI Pac (electric add-on)	See Comments	Obsolete - no replacements available
	SPX hydraulic pumps	See Comments	Obsolete - no replacements available
MF4046	EI Pac (electric add-on)	See Comments	Obsolete - no replacements available
	SPX hydraulic pumps - single leg application		
	SPX hydraulic pumps - multi leg application		
1789-AC	SPX pump # 1067 & 1017	1516	Obsolete - no replacements available
1791-AC	SPX pumps	1456	4.5 inch motor (Gold) 24 VDC Splined shaft
MF4302	SPX DG 8026	See Comments	Available from Equalizer only as a Refurbished/used motor-12 VDC. Call Equalizer service department for replacement
39200513	MTE pump # 2015, 2016, 2017, 2142, 3126, 3126s, 3170	2427	MTE Uni 3.7 inch motor 12 VDC
39200443	MTE pump # 1551	2006	MTE Uni 4.5 inch motor 12 VDC
39200522	MTE pump # 2390, 2532, 2542	2605	MTE BI Rot 3.7 inch 2 terminal motor 12 VDC
39200485	MTE pump # 1531,1636	2011	MTE 3 inch uni 12 VDC
39200520	MTE pump # 3040, 3041, 3043, 2727 ,2754, 3195, 3200, 3201	2751	MTE 3 inch 2 terminal Bi Rot 12 VDC
39200516	MTE 1551, 2998, 3136	2069	MTE 4.5 inch 2 terminal 24 VDC
SAE J1171	Parker/Olydyne Bi Rot pump	See Comments	Obsolete - no replacements available
011-562-1097	EL Pac 1 Bison motor/gear box	2708	Obsolete - no replacements available
030-562-3097	EL Pac 1 Bison motor/gear box	See Comments	Obsolete - no replacements available
011-562-1028	EI Pac 2 Bison motor/gear box	2550	Replacement motor only is not available, it must be purchased as a motor/gearbox assembly.
030-562-3028	EI Pac 2 Bison motor/gear box	2550	Replacement motor only is not available, it must be purchased as a motor/gearbox assembly.
853208J	Stabi-Lite motor gearbox	6836	Replacement motor only is not available, it must be purchased as a motor/gearbox assembly.
K01348D500	Electric Slide motor gearbox Klauber	2097	Replacement motor only is not available, it must be purchased as a motor/gearbox assembly.